

# TECHNICAL DATA SHEET



**GIORDANI  
GIANCARLO**  
WORK PROTECTION ITEMS



## 1034100/1034200

Fireproof suit made of **XISPA**  for pentavalent protection.

Composition: 50% cotton; 39% modified acrylic type F, 10% viscose, 1% antistatic;

Weight : 340 g/sqm+/- 5%

**1034100** Jacket with shirt collar, set-in sleeves, elasticated at the wrist. Front opening with press studs covered by a flap secured with concealed hook-and-loop fastening. One pocket at the waist and one on the chest, closed with a flap secured at the sides with concealed Velcro.

Option to apply 5 cm grey retro-reflective bands on the biceps and chest circumference (code **1134100**).

**1034200** Trousers with elasticated waistband and belt loops. Front opening with buttonhole/button and press studs covered by a flap. Two slash pockets. One back patch pocket with flap fastened at the sides with Velcro. One large side pocket (left side) with flap fastened at the sides with Velcro.

Option to apply 5 cm grey retro-reflective strips on the calf (code **1134200**).

Option to manufacture garments in the following colours: orange, grey, blue.

**UNI EN ISO 11612 A1, B1, C1, D2, E2, F1**

**UNI EN ISO 11611 Classe 1 A1**

**EN 1149-5**

**UNI EN 17353 Tipo B3**

**CEI EN 61482-2 APC1 -4kA**



# SIZE CHART



**GIORDANI  
GIANCARLO**

WORK PROTECTION ITEMS

JACKET					
	Chest circumference	Shoulder width (from shoulder to shoulder)	Shoulder (from neckline to shoulder)	Sleeve length	Jacket length
44	105	42,5	15,1	62	78
46	109	44	15,5	63	79
48	113	45,5	15,9	64	80
50	117	47	16,3	65	81
52	121	48,5	16,7	66	82
54	125	50	17,1	67	83
56	129	51,5	17,5	68	84
58	133	53	17,9	69	85
60	137	54,5	18,3	69,5	86
62	141	56	18,7	70	87
64	145	57,5	19,1	70,5	88



TROUSERS				
	Trousers length with belt	Waist	Trousers crotch	Inside leg length
44	105	82	24	78
46	106,5	86	24,5	79
48	108	90	25	80
50	109,5	94	25,5	81
52	111	98	26	82
54	112,5	102	26,5	83
56	114	106	27	84
58	115,5	110	27,5	85
60	116,5	114	28	85,5
62	117,5	118	28,5	86
64	118,5	122	29	86,5



## WARNINGS

Store the garment in its original packaging in a cool, dry place, away from heat sources and protected from light. Before each use, check that the garment is in perfect condition. If it is not intact, replace it. Carefully follow the instructions on the label and the information provided in the Information Note to keep the garment in good condition.



Maximum washing temperature 60°C normal cycle



Do not bleach



Tumble dry at maximum temperature of 60°C



Iron at maximum Temperature of 150°C



Professional dry cleaning with tetrachloroethylene and all solvents listed under symbol F normal cycle