

TECHNICAL DATA SHEET



**GIORDANI
GIANCARLO**
WORK PROTECTION ITEMS



10301001/10302001

Flame retardant fabric **marlanplus** set, suitable for welding and protection against molten metal splashes. Made from 60% flame-retardant viscose, 20% wool, 10% polyamide, and 10% Tencel fabric, with a 100% flame-retardant cotton **lining**.

The PPE is made from fabric with a total weight of **460 g/m²**.

10301001 - Jacket with mandarin collar; front closure with snap buttons covered by a flap secured with Velcro. Cuffs with flame-retardant knit fabric. Three patch pockets closed with flaps and snap buttons (chest and waist); set-in sleeves.

10302001 – Trousers with front closure featuring snap buttons, button covers, and a button at the waist. Belt loops at the waist. Two side pockets at the waist and two patch pockets: one on the back and one on the side, each with a flap and a snap button.

Available colors: navy blue; green, red, and orange (upon request).

Reflective strips available upon request (jacket – **10311001** / trousers - **10312001**).

Available sizes: 44 to 64.

UNI EN ISO 11612 A1 B1 C1 D3 E3 F1 Cryolite test

UNI EN ISO 11611 A1 Class 1

UNI EN 17353

FLAME-RETARDANT CERTIFICATE VALID FOR 50 WASHES



SIZE CHART



**GIORDANI
GIANCARLO**
WORK PROTECTION ITEMS

JACKET					
	Chest Circumference	Shoulders width (from shoulder to shoulder)	Shoulder (from neck to shoulder)	Sleeve length	Jacket length
44	105	42,5	15,1	62	78
46	109	44	15,5	63	79
48	113	45,5	15,9	64	80
50	117	47	16,3	65	81
52	121	48,5	16,7	66	82
54	125	50	17,1	67	83
56	129	51,5	17,5	68	84
58	133	53	17,9	69	85
60	137	54,5	18,3	69,5	86
62	141	56	18,7	70	87
64	145	57,5	19,1	70,5	88



TROUSERS				
	Trousers length with belt	Waistline	Crotch	Inside leg length
48	108	90	25	80
50	109,5	94	25,5	81
52	111	98	26	82
54	112,5	102	26,5	83
56	114	106	27	84
58	115,5	110	27,5	85
60	116,5	114	28	85,5
62	117,5	118	28,5	86
64	118,5	122	29	86,5



WARNINGS:

Store the garment in its original packaging in a cool, dry place, away from heat sources and protected from light. Before each use, check that the garment is in perfect condition; if it is not intact, replace it.

Follow the instructions on the label and the guidance provided in the Information Sheet carefully to keep the garment in good condition.



Maximum washing temperature: 60°C normal cycle



Do not bleach



Tumble dry at 60°C



Iron at a maximum temperature of 150°C



Professional dry cleaning with tetrachloroethylene and all solvents listed under symbol F normal cycle.