

TECHNICAL DATA SHEET



**GIORDANI
GIANCARLO**
WORK PROTECTION ITEMS



1035100/1035200

Flame – retardant fabric **marlanplus** coverall suitable for welding and protection against molten metal splashes. Made from a fabric comprising 60% flame-retardant viscose, 20% wool, 10% polyamide and 10% Tencel.

The PPE is made from **350 g/m² fabric**.

1035100 - Jacket with mandarin collar; front fastening with press studs covered by a flap secured with Velcro. Cuffs with flame-retardant knit fabric. Three patch pockets closed with a flap and press stud (on the chest and at the waist); set-in sleeves.

1035200 - Trousers with front fastening featuring press studs, button covers and a button at the waist. Belt loops at the waist. Two side pockets at the waist and two patch pockets: one at the back and one on the side, each with a flap and press stud. Reflective strips available on request: jacket model **1135100** / trousers model **1135200**.

Colours available: navy blue; green, red and orange (on request).

Sizes available from 44 to 64.

UNI EN ISO 11612 A1 B1 C1 D3 E3 F1 test for cryolite

UNI EN ISO 11611 A1 Class 1

UNI EN 17353

FIRE-RETARDANT CERTIFICATE VALID FOR 50 WASHES



SIZE CHART



**GIORDANI
GIANCARLO**
WORK PROTECTION ITEMS

JACKET					
	Chest Circumference	Shoulders width (from shoulder to shoulder)	Shoulder (from neck to shoulder)	Sleeve length	Jacket length
44	105	42,5	15,1	62	78
46	109	44	15,5	63	79
48	113	45,5	15,9	64	80
50	117	47	16,3	65	81
52	121	48,5	16,7	66	82
54	125	50	17,1	67	83
56	129	51,5	17,5	68	84
58	133	53	17,9	69	85
60	137	54,5	18,3	69,5	86
62	141	56	18,7	70	87
64	145	57,5	19,1	70,5	88



TROUSERS				
	Trousers length with belt	Waistline	Crotch	Inside leg length
44	105	82	24	78
46	106,5	86	24,5	79
48	108	90	25	80
50	109,5	94	25,5	81
52	111	98	26	82
54	112,5	102	26,5	83
56	114	106	27	84
58	115,5	110	27,5	85
60	116,5	114	28	85,5
62	117,5	118	28,5	86
64	118,5	122	29	86,5



WARNINGS:

Store the garment in its original packaging in a cool, dry place, away from heat sources and protected from light. Before each use, check that the garment is in perfect condition; if it is not intact, replace it.

Follow the instructions on the label and the guidance provided in the Information Sheet carefully to keep the garment in good condition.



Maximum washing temperature: 60°C normal cycle



Do not bleach



Tumble dry at 60°C



Iron at a maximum temperature of 150°C



Professional dry cleaning with tetrachloroethylene and all solvents listed under symbol F normal cycle.