

# TECHNICAL DATA SHEET



**GIORDANI  
GIANCARLO**  
WORK PROTECTION ITEMS



**9602101- 9602201**

Multirisk suit in fabric **TECAPRO®**

Jacket with mandarin collar and Velcro insert. Set-in sleeves, internal elastic on half cuff. Front opening with snap buttons covered by a flap secured with covered hook-and-loop fastening. Two pockets at the waist and one on the chest, closed with a flap secured at the sides and covered by Velcro. Possibility of applying grey reflective bands on the biceps, chest and back. Trousers with front opening by covered snap button, applied to the belt, and zip. Two slash pockets closed with flaps attached to the sides and Velcro. One back pocket closed with a flap secured to the sides by Velcro. One large side pocket (left side) closed with a flap secured to the sides by Velcro. Elasticated waistband with belt loops.

Possibility of applying grey reflective strips to the calf.

Fabric composition: 74% COTTON; 25% POLYESTER 1% STATIC-CONTROL

Fabric with permanent fireproof finish with comfort-control and hydro-tec.

Fabric weight: 320 g/m<sup>2</sup> (± 5%).

**UNI EN ISO 11612 A1-A2, B1, C1, E3, F1**

**UNI EN ISO 11611 Classe 1 A1-A2**

**EN 1149-5 UNI EN 13034 Tipo 6CEI**

**EN 61482-2 APC1 -4kA**

**FIREPROOF CERTIFICATION AT 50 WASHES**



# SIZE CHART



**GIORDANI  
GIANCARLO**  
WORK PROTECTION ITEMS

JACKET					
	Chest Circumference	Shoulder width (from shoulder to shoulder)	Shoulder (from neck to shoulder)	Sleeve length	Jacket length
44	105	42,5	15,1	62	78
46	109	44	15,5	63	79
48	113	45,5	15,9	64	80
50	117	47	16,3	65	81
52	121	48,5	16,7	66	82
54	125	50	17,1	67	83
56	129	51,5	17,5	68	84
58	133	53	17,9	69	85
60	137	54,5	18,3	69,5	86
62	141	56	18,7	70	87
64	145	57,5	19,1	70,5	88



TROUSERS				
	Trouser length with belt	Waistline	Crotch	Inside leg length
44	105	82	24	78
46	106,5	86	24,5	79
48	108	90	25	80
50	109,5	94	25,5	81
52	111	98	26	82
54	112,5	102	26,5	83
56	114	106	27	84
58	115,5	110	27,5	85
60	116,5	114	28	85,5
62	117,5	118	28,5	86
64	118,5	122	29	86,5

## WARNINGS:

Store the garment in its original packaging in a cool, dry place, away from heat sources and protected from light. Before each use, check that the garment is in perfect condition. If it is not intact, replace it.

Carefully follow the instructions on the label and the information provided in the Information Note to keep the garment in good condition.



Maximum washing temperature  
60°C, standard cycle



Do not bleach



Tumble dry  
at 60°C



Iron at  
a maximum  
temperature  
of 150°C



Professional dry cleaning  
using tetrachloroethylene and  
all solvents listed  
under symbol F  
(standard cycle)